




Schöck Isokorb® XT/T type K-HV/BH/WO/WU

















Be sure to fill the compression joint with in-situ concrete! Joint width ≥ 100 mm.








Step formwork in accordance with work plan.
























Be sure to fill the compression joint with in-situ concrete! Joint width ≥ 100 mm.








Step formwork in accordance with work plan.



























Be sure to fill the compression joint with in-situ concrete! Joint width ≥ 100 mm.




Step formwork in accordance with work plan.











Be sure to fill the compression joint with in-situ concrete! Joint width ≥ 100 mm.





Step formwork in accordance with work plan.

